

The Board of Education of

School District No. 83 (North Okanagan-Shuswap)
341 Shuswap Street SW, Box 129, Salmon Arm, BC, V1E 4N2
Phone: (250) 832 2157 Fax: (250) 832 9428

	OPEN		WRK		COMP	
W/O #	DATE	REQUEST	TYPE	ROOM	DATE	CRAFT
		MECHCANCAL				
	0/00/00/0	UPGRADE DDC			0/0/00/0	
64950	2/20/2018	SYSTEM	BP		9/6/2019	
		**2018-19 SNOW				
70400	40/00/0040	REMOVAL DO NOT	D.4		4/0/0000	Casustani
70408	10/23/2018	CLOSE**	RM		1/9/2020	Secretary
		ASBESTOS REVIEW AND				
		UPDATE PLAN AS				
		PER WORK SAFE				
70706	11/1/2018	REQUIRMENTS	PM		10/17/2019	CARPENTER
70700	11/1/2010	GYM DOORS	FIVI		10/11/2019	CARFLITTER
		SOUTH EAST				
		CORNER OF GYM				
		VERY ROTTEN.				
		THEY NEED				
71200	11/16/2018	REPLACED	RM	GYM	11/26/2019	CARPENTER
		BUILDING - SITE -				
		SPRING				
		GROUNDS CLEAN				
73582	2/27/2019	UP- ANNUAL PM	PM		11/4/2019	GROUNDS
		BUILDING - SITE -				
		JUMP PIT				
		REPLENISH AND				
		PLAYFIELD				
		INSPECTION AND				
74050	0/00/0040	REPAIR - ANNUAL	D. 4		4.4./4./00.4.0	ODOLINDO
74350	3/28/2019	PM	PM		11/4/2019	GROUNDS
		HEATING -				
		EXPANSION TANK SERVICE - SEMI				
74405	3/28/2019	ANNUAL PM	PM		9/18/2019	PLUMBER
1	3/20/2019	BUILDING- SITE -	I IVI		3/10/2019	LOWDLIX
		PLAYGROUND				
		EQUIPMENT				
		INSPECTION &				
		MINOR REPAIR -				
74280	3/28/2019	SEMI ANNUAL PM	PM		11/4/2019	GROUNDS
		BUILDING - SITE -				
74303	3/28/2019	CLEAN AND	РМ		11/20/2019	GROUNDS
7 1000	0,20,2010	ULL/ 1 / 1	1 171	I	11/20/2010	211221120

	1	INSPECT CATCH	I	1	I	
		BASINS - ANNUAL				
		PM				
		BUILDING - SITE -				
		PRUNING				
		SHRUBS/TREES -				
74333	3/28/2019	ANNUAL PM	PM		10/11/2019	GROUNDS
		BUILDING-SITE-				
		MOWING AND				
74910	4/25/2019	TRIMMING	PM		11/13/2019	GROUNDS
		BUILDING - SITE -				
		FERTILIZATION OF				
74938	4/25/2019	PLAYFIELDS - APR/SEPT PM	PM		11/13/2019	GROUNDS
74930	4/25/2019	BUILDINGS -	FIVI		11/13/2019	GROUNDS
		ROOFING, FACIA,				
		GUTTERS, DRAIN				
		REPAIRS AND				
		INSPECTION-				
75017	4/26/2019	YEARLY PM	PM	ROOF	10/15/2019	CARPENTER
		MAIN HALL				
		FLOORING JOINTS				
		IN LINOLEUM ARE				
		SEPERATING.				
		NEED REOAIR BEFORE		MAIN		
75800	5/28/2019	DAMAGED.	RM	HALLWAYS	10/17/2019	CARPENTER
70000	0/20/2010	TECH REQUEST	TXIVI	TITALLEVITATIO	10/11/2010	O/ II II EI II EI I
		PLEASE MOUNT				
		PROJECT IN				
		ROOM 12.				
		BUDGET CODE				
		000-1-02-59000-022				
		COMPUTER				
		EQUIPMENT				
		DISTRICT				
		ACCOUNT SEE TEACHER ON				
		JUNE 28TH FOR				
		PROJECTOR				
76321	6/17/2019	LOCATION	SBF	ROOM 12	11/10/2019	ADMIN
. 5021	3, 1.72010	TEACH REQUEST	02.		1.7.1072010	
		PLEASE MOUNT				
		PROJECT IN				
		ROOM 12.				
		BUDGET CODE				
		000-1-02-59000-022				
070004		COMPUTER				
076321-	0/40/0040	EQUIPMENT	CDE	DOOM 40	44/0/0040	CADDENTED
10	6/18/2019	DISTRICT	SBF	ROOM 12	11/6/2019	CARPENTER

		ACCOUNT SEE TEACHER ON JUNE 28TH FOR PROJECTOR LOCATION				
076321- 11	6/18/2019	TECH REQUEST PLEASE MOUNT PROJECTOR IN ROOM 12. BUDGET CODE 000-1-02-59000-022 COMPUTER EQUIPMENT DISTRICT ACCOUNT SEE TEACHER ON JUNE 28TH FOR PROJECTOR LOCATION	SBF	ROOM 12	10/25/2019	ELEC
76482	6/25/2019	PLUMBER GIRL'S WASHROOM TOILET OUT OF ORDER (NEAR OFFICE IN HALLWAY)	RM		9/19/2019	
76613	6/27/2019	HEATING - BOILER SYSTEM CHECK & PUMP MAINTENANCE - ANNUAL NOVEMBER PM	PM		9/16/2019	PLUMBER
76789	7/5/2019	PAINTERS - REPAIR PAINT DAMAGE THROUGHOUT SCHOOL	RM		10/22/2019	PAINTER
77196	8/21/2019	drywall - please repair hole in principals office and just outside of principals office	RM		9/4/2019	CARPENTER
071200- 15	8/22/2019	GYM DOORS SOUTH EAST CORNER OF GYM VERY ROTTEN. THEY NEED REPLACED	RM	GYM	11/29/2019	PAINTER

77255	8/27/2019	IN ADDITION TO 077196 - CLASSROOMS WITH HOLES AND PAINT ISSUES AFTER COMPONENTS MOVED - PLEASE SEE PRINCIPAL	RM	10/22/2019	PAINTER
11255	0/21/2019	PLEASE REMOVE	KIVI	10/22/2019	PAINTER
77284	8/28/2019	BROKEN COAT HOOKS IN COATROOM OF ROOM #12, AND REPLACE AMY MISSING HOOKS	RM	9/5/2019	CARPENTER
		HAULING PLEASE DELIVER 30 TABLES AND 190 CHAIRS TO PARKVIEW FOR OUR BACK TO SCHOOL BEEF ON A BUN ON TUESDAY, SEPTEMBER 17,			
77299	8/29/2019	2019	DEL	9/17/2019	DELIVERY
77325	8/30/2010	REPLACE EXREIOR DOORS ON BOTH GIRLS AND BOYS CHANGE ROOM AS THY ARE BOTH ROTTING OFF AT BOTTOM AS WELL	DM	12/5/2010	CARPENTER
77325	8/30/2019	AS DELAMING. BUILDING - SITE - AERATION OF	RM	12/5/2019	CARPENIER
	0/0/22:-	PLAYFIELDS & MARK ING SPRINKLER HEADS - BI	D14	44/00/2015	
77416	9/3/2019	ANNUAL PM HEATING - BOILER	PM	11/20/2019	GROUNDS
77494	9/3/2019	SYSTEM START UP - ANNUAL PM	PM	10/29/2019	HVAC
77506	9/3/2019	HEATING - FURNACE SYSTEM START UP- ANNUAL PM	PM	10/29/2019	HVAC

		HVAC - EXHAUST				
		FAN INSPECTION				
		AND BELT CHANGE -				
77548	9/3/2019	ANNUAL PM	РМ		10/22/2019	HVAC
		GIRL'S				
		CHANGEROOM				
77633	9/3/2019	DRAIN IS BACKFILLING	RM	CHANGEROOM	9/17/2019	PLUMBER
77000	3/3/2013	GIRL'S	IXIVI	OHAIVOLIVOON	3/11/2013	1 LOWDLIX
		WASHROOM IN				
	- /- /	HALLWAY - TOILET				
77635	9/3/2019	IS NOT WORKING PLUMBER BOY'S	RM	WASHROOM	9/17/2019	PLUMBER
		WASHROOM NEAR				
		MAIN ENTRANCE				
		SINK DRAIN HAS A				
77691	9/4/2019	HOLE IN IT.	RM	WASHROMM	9/17/2019	PLUMBER
		PLUMBER BOY'S WASHROOM IN				
		THE POD, URINAL				
		NOT FLUSHING				
77728	9/5/2019	AUTOMATICALLY.	RM	WASHROOM	9/10/2019	PLUMBER
		DRAINAGE IN				
		PARKING LOT - PICTURES SENT				
		TO TREVOR AND				
77772	9/9/2019	GLYNN	BD		11/6/2019	GROUNDS
		EXTREME MILDEW				
		SMELL IN FRONT ENTRANCE OF				
77776	9/9/2019	SCHOOL.	INS	ENTRANCE	12/11/2019	PLUMBER
	0,0,20.0	PLUMBING - HOT				
		WATER TANK IN				
		CRAWL SPACE LEAKING - SEE				
77788	9/9/2019	GLYNN W.	RM		9/16/2019	PLUMBER
7.700	0,0,2010	EXTREME MILDEW	1 3141		0,10,2010	· LOWDLIN
		SMELL IN FRONT				
077776-	0/40/0040	ENTRANCE OF	INIC		44/44/0040	11)/40
13	9/10/2019	SCHOOL. ELECTRICIAN -	INS	ENTRANCE	11/14/2019	HVAC
		ALARM HAS BEEN				
		GOING IN SCHOOL				
		FOR OVER AN				
		HOUR (6 AM) - AS				
		PER SECURITY COMPANY. MAP				
		INDICATES				
77909	9/12/2019	TROULE BUT NOT	RM		9/12/2019	ELEC

		INDICATING LOCATION. SPOKE TO KELLY IN OPERATIONS - MARCUS DISPATCHED TO PARKVIEW AT 7:20				
		AM				
77943	9/13/2019	MILDEW/MUSTY SMELL ON WEST END OF MAIN HALL - REPORTED TO ME BY 2 STAFF MEMBERS.	INS	HALLWAY	11/14/2019	PLUMBER
	0/40/0040	ODOUR PERSISTS IN WEST WING OF SCHOOL, MAIN FOYER AND OFFICE AREA. WEST WING IS NOW CLOSED			10/00/0010	
77972	9/16/2019	INDEFEINTLEY PLUMBING - HOT	INS		12/23/2019	PLUMBER
077788- 10	9/16/2019	WATER TANK IN CRAWL SPACE LEAKING - SEE GLYNN W.	RM		9/16/2019	CARPENTER
077788-		PLUMBING - HOT WATER TANK IN CRAWL SPACE LEAKING - SEE				
077972-	9/16/2019	GLYNN W. ODOUR PERSISTS IN WEST WING OF SCHOOL, MAIN FOYER AND OFFICE AREA. WEST WING IS NOW CLOSED	RM		9/11/2019	
10	9/18/2019	INDEFEINTLEY ODOUR PERSISTS IN WEST WING OF SCHOOL, MAIN FOYER AND OFFICE AREA.	INS		11/8/2019	CARPENTER
077972- 13	9/18/2019	WEST WING IS NOW CLOSED INDEFEINTLEY	INS		10/28/2019	HVAC

077972-	0/00/0040	ODOUR PERSISTS IN WEST WING OF SCHOOL, MAIN FOYER AND OFFICE AREA. WEST WING IS NOW CLOSED		40/4/0040	OTUED
20	9/20/2019	INDEFEINTLEY	INS	12/4/2019	OTHER
78178	9/23/2019	11:56 PM FALSE ALARM ON WEST HALL DOORS. ZONE DELETED UNTIL REPAIRS CAN BE MADE.	ALC	9/23/2019	ELEC
70040	0/00/0040	WATER - WASTE - TOILET AND URINAL AUTO FLUSH VALVE MAINTENANCE -		11/0/0040	
78319	9/30/2019	YEARLY PM	PM	11/8/2019	PLUMBER
78995	10/23/2019	5:12 AM MOTION. CASS FROM GRAYDON ALARM CALLED MOTION IN AREA 62.	ALC	10/25/2019	CUSTODIAN
70000	10/00/0010	REPLACE FURNACES IN GYM STORAGE	55	44/40/0040	111/40
79090	10/29/2019	ROOM	BP	11/13/2019	HVAC
79106	10/29/2019	ASBESTOS REVIEW AND UPDATE PLAN AS PER WORK SAFE REQUIRMENTS	PM	10/28/2019	CARPENTER
		ELECTRICAL- SYSTEM - DAYLIGHT SAVINGS TIME CHANGE -			
79184	10/29/2019	ANNUAL PM	PM	11/4/2019	ELEC
79229	10/29/2019	HVAC - FILTER CHANGE - ROOF TOP UNITS, AIR HANDLING UNITS AND FURNACES - QUARTERLY PM	PM	10/22/2019	HVAC
13223	10/20/2019	UPS BACK UP PAR POWER SUPPLY FOR PA SYSTEM	1 101	10/22/2019	TIVAO
79394	11/4/2019	NOT WORKING	RM	11/13/2019	ELEC

079090- 10	11/6/2019	REPLACE FURNACES IN GYM STORAGE ROOM	BP	12/5/2019	CARPENTER
79501	11/7/2019	HAULING - PLEASE HAUL WOODEN CHAIRS AND FURNITURE THAT IS NOT USED TO WORKS COMPLEX - SEE PRINCIPAL OR CHIEF CUSTODIAN - CURRENTLY IN ACTIVITY ROOM	DEL	11/12/2019	DELIVERY
79502	11/7/2019	CARPENTER - PLEASE REMOVE ALL ELEMENTARY COAT HOOKS THAT WERE PUT UP AT ERS (4 CLASSROOMS) - PLEASE INSTALL 1 EACH IN ROOMS #16 AND 17 UNDER CURRENT COAT HOOKS - REMAINDER CAN BE STORED AT PARKVIEW	RM	12/11/2019	CARPENTER
79500	11/7/2019	CARPENTER - PLEASE HANG SCHOOL COMPOSITE PHOTO - CURRENTLY STORED IN OFFICE	RM	1/23/2020	CARPENTER
79577	11/12/2019	HAULING - PLEASE HAUL EMPTY BOXES AND PACKING SUPPLIES FROM ROOM #8 TO WORKS COMPLEX	DEL	11/15/2019	DELIVERY
79591	11/13/2019	HAULING - PLEASE HAUL ROLLING BULLETIN BOARD/CHALK	DEL	11/14/2019	DELIVERY

		BOARD OUTSIDE OF ROOM #5 TO				
		OPERATIONS				
79585	11/13/2019	FILL IN MISSING GRATE IN EXTERIOR BOOT SCRAPER PIT (3/4 PLYWOOD TEMP) ALSO DELIVER 2 BOXES OF CEILING TILE.	RM		11/13/2019	CARPENTER
077972-		ODOUR PERSISTS IN WEST WING OF SCHOOL, MAIN FOYER AND OFFICE AREA. WEST WING IS NOW CLOSED				
14	11/14/2019	INDEFEINTLEY	INS		11/14/2019	PLUMBER
79632	11/14/2019	INTRUSSION SYSTEM TROUBLES. SEVERAL DEVICES WERE TURNED OFF. ZONE 23 - ROOM 20 PIR: ZONE 54 - GYM SE DRS: ZONE 56 - PRINC OFF PIR: ZONE 75 - WEST HALL DOORS	RM		11/13/2019	ELEC
		HEAT INDIGENOUS ED ROOM (BEHIND ROOM 12 PLEASE SET THE HEAT TO COME ON IN THE INDIGENOUS ED ROOM ON WEDNESDAY, THURSDAY AND FRIDAY. VERY		INDIGENOUS		
79675	11/15/2019	COOL IN THERE.	RM	ED	11/18/2019	HVAC
		GROUNDS PLEASE PICK UP BAGS OF SALT RECENTLY DROPPED OFF AT				
79681	11/15/2019	PARKVIEW. WE	RM		11/18/2019	GROUNDS

1 1		HAVE AN	İ]		
		ABUNDANCE IN				
		OUR STORAGE				
		AREA FOR THE				
		WINTER, THANK				
		YOU. SANDRA				
		CELING TILE IN				
		-				
		POD IN ROON #14 STILL HAS NOT				
		BEE PUT BACK -				
		KIMCO SAID IT				
70774	11/00/0010	WOULD BE DONE	DM		40/0/0040	CADDENTED
79774	11/20/2019	2 WEEKS AGO	RM		12/3/2019	CARPENTER
		HEATING -				
		THERMOMETER IN				
		ROOM #14				
		CYCLING FROM CL TO HT EVERY 5				
70000	11/21/2019		DD		11/06/0010	111/40
79803	11/21/2019	SECONDS	BD		11/26/2019	HVAC
		REPAIR DOOTR CLOSURE IN IND				
		ED ROOM - AS				
		PER FACIKLITY				
70924	11/22/2010	TOUR	RM		12/2/2010	CARPENTER
79824	11/22/2019	REPAIR HANDLES	KIVI		12/3/2019	CARPENIER
		ON CUPBOARD IN				
		ROOM 14 AS PER				
79825	11/22/2019	FACILITY TOUR	RM		12/3/2019	CARPENTER
79023	11/22/2019	REPAIR EXTERIOR	KIVI		12/3/2019	CARPENIER
		DOOR BY				
		INTERSECTION AS				
		PER FACIKITY				
79826	11/22/2019	TOUR	RM		12/3/2019	CARPENTER
79020	11/22/2019	PAINT - PAINT	IXIVI		12/3/2019	CARFLITTER
		TOUCH UPS AS PER POST				
		PARKVIW MOVE -				
		AS PER FACILITY				
79823	11/22/2019	TOUR	RM		12/11/2019	PAINTER
1 3023	11/22/2019	HEATING - UPPER	IXIVI		12/11/2019	IAINILI
		VENT IN VP				
		OFFICE IS				
		BLOWING COLD				
79875	11/26/2019	AIR BRRRRR	RM		12/13/2019	HVAC
7 307 0	. 1/20/2010	10:00 PM	1 (14)		. 2, 10,2010	,.
		BURGLARY				
		ALARM. PIECE OF				
		PAPER ATTACHED				
		TO COMPUTER				
80263	12/1/2019	LAB WINDOW	ALC		12/3/2019	CUSTODIAN
33200	, ., _0 10		, ,	<u> </u>	, 0, _0 10	3331321/114

		FELL AND SET OFF MOTION ALARM.				
80230	12/3/2019	BARRICADES REQUIRED IN BACK OF SCHOOL WHERE SNOW SLIDES OFF ROOF	RM		12/5/2019	GROUNDS
30230	12,6,20.10	PLEASE MOVE HOOLA HOOP RACKS IN PE EQUIPMENT ROOM TO BE ABOVE THE BADMINTON RAQUETS -AS PER THE FACIITY			.2.6,26.10	
80328	12/6/2019	TOUR	RM		1/23/2020	CARPENTER
		EXTERIOR DOOR TO ROOM #13 DOES NOT CLOSE - SAFETY AND				
80355	12/9/2019	COLD ISSUE PLEASE ORDER	RM		12/17/2019	CARPENTER
		AND INSTALL NEW LATCH ON BOYS INTERMEDIATE BATHROOM STALL - SEE PRINCIPAL				
80379	12/9/2019	OR CUSTODIAN	RM		1/23/2020	CARPENTER
		PLUMBING - LADIES STAFF WASHROOM BY OFFICE - 1XT STALL - NO				
80408	12/10/2019	WATER	RM		1/27/2020	PLUMBER
80421	12/11/2019	PLUMBING - TAP IN ROOM #17 9 IS SPRAYING OUT	RM		1/27/2020	PLUMBER
90/21	12/11/2010	PLUMBING - FOUNTAIN LEAKING BY PRIMARY POD - SEE CHIEF	RM		1/27/2020	DITIMPED
80431	12/11/2019	CUSTODIAN Sink spout has a pin	KIVI		1/21/2020	PLUMBER
90540	10/10/2010	hole so water shoots sideways out of	RM	Poom 17	1/0/2020	DILIMPED
80540	12/18/2019	hole.	L/IAI	Room 17	1/9/2020	PLUMBER

		Pod tap (Room 12-				
80541	12/18/2019	15) has a constant drip	RM	Room 12 - 15	1/27/2020	PLUMBER
00011	12, 13, 23.13	Please set heat to		110011112 10	172172020	· LOWBLIX
		23 C. The heater is				
90557	10/10/2010	not on and the room	RM	Doom 12A	1/0/2020	LIVAC
80557	12/18/2019	is quite chilly HEAT ROOMS 3	KIVI	Room 13A	1/8/2020	HVAC
		AND 5 ARE				
		EXTREMELY				
		COLD. 10				
80567	12/19/2019	DEGREES AND 13 DEGREES	RM		12/19/2019	HVAC
00001	12/13/2013	9:58 AM FIRE	IXIVI		12/13/2013	TIVAO
		TROUBLE AC				
		FAILURE. WENT				
		TO SITE CHECKED SCHOOL & BOILER				
		ROOM. CHECKED				
		INTRUSION LOGS				
		AND HYDRO				
80709	1/1/2020	SITES.	ALC		1/7/2020	PLUMBER
		PLEASE PICK UP AUTOSCRUBBER				
		FROM PARKVIEW				
		AND BRING IN				
		FOR REPAIR.				
		ISSUE IS ELECTRICAL AND				
		ROSS SAID				
		ELECTRICIANS				
00000	4/40/0000	WILL ASSESS IT IN	551		4/00/0000	DEL 11 (ED) (
80800	1/10/2020	THEIR SHOP. CUSTODIAL	DEL		1/23/2020	DELIVERY
		REPAIR AUTO				
		SCRUBBER,				
		BRUSHES NOT				
		ENGAGING.				
		PLEASE REPAIR AND SEND BACK				
		TO PARKVIEW.				
		KEY IS IN THE				
80863	1/14/2020	ENVELOPE.	DEL		1/15/2020	DELIVERY
		LIGHT FIXTURE IN HALL BETWEEN				
		MEDICAL ROOM				
		AND STAFF				
		WASHROOM				
80934	1/16/2020	LOOKS AS IF IT IS ABOUT TO FALL -	RM		1/21/2020	ELEC
00934	1/10/2020	ADOUT TO FALL:	IXIVI		1/2 1/2020	

		SAFETY CONCERN					
81025	1/21/2020	Leaking faucet in room #19	RM	1	19	1/27/2020	PLUMBER